

EAST - [Untitled1:1]

File View Edit Tools Window Help

Drafts Pending Active Failed Saved (103) (65/429).CCLS. (75) (65/397).CCLS. Favorites Tagged (18) UDC Queue Trash

Search List Browse Queue Clear DBs USPAT Highlight all hit terms initially

65/397

	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Document ID	Issue Date	Pages	Title	Current OR	Current XRef	Retrieval Class
1	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6598425 B1	20030729	15	Method for collecting soot	65/17.4	427/472; 427/473;	65/397 Hawl
2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6574994 B2	20030610	27	Method of manufacturing multi-segmented optical fiber and preform	65/391	65/397; 65/398;	65/397 Cain
3	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6550277 B1	20030422	6	Quartz glass body for optical component and process for manufacture thereof	65/17.4	501/905; 65/104;	65/397 Uebt
4	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6519975 B1	20030218	14	Method of making fluorinated rare earth doped glass and glass-ceramic waveguides	65/384	65/33.3; 65/33.7;	65/397 Bang
5	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6502426 B2	20030107	13	Oxygen doping of silicon oxyfluoride glass	65/111	428/428; 430/5;	65/397 Moon
6	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6499317 B1	20021231	21	Synthetic quartz glass and method for production thereof	65/378	501/30; 501/40;	65/397 Ikutz
7	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6477864 B2	20021112	4	Method of purifying natural or synthetic silica, and application thereof to depositing	65/391	427/446; 427/452;	65/397 Drou
8	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6474108 B2	20021105	19	Fiber preform method with a hot drill-in step for a Ge-doped tube and an F-doped	65/397	65/112; 65/404;	65/397 Onish
9	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6474107 B1	20021105	8	Fluorinating an optical fiber preform in a pure aluminum oxide muffle tube	65/397	65/374.13; 65/426;	65/397 Dabb
10	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6467313 B1	20021022	15	Method for controlling dopant profiles	65/399	65/378; 65/390;	65/397 Chu,
11	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6422042 B1	20020723	15	Rit method of making optical fiber having	65/397	65/412; 65/424	65/397 Berk



- Drafts
- Pending
- Active
 - ocr L1: (10) (glass same (fluorine or F) same Dop\$4) and ((strip\$4 or remov\$3) adj dop\$4)
- Failed
- Saved
 - (2) glass same fluorine same dopant same migrat\$3
 - (0) glass same dopant same purity same layer
 - (0) glass same dopant same purity same layer
 - (31) glass same dopant same purity same layer
 - (31) glass same dopant same purity same layer
 - (0) glass same dopant same purity same (layer or clad\$3) same (part\$4 adj sinter\$3)
 - (0) glass same dopant same purity same (layer or clad\$3) and (part\$4 adj sinter\$3)
 - (1) glass same dopant same purity same (layer or clad\$3) same dens\$4
 - ocr (16) glass same dopant same purity same layer
 - (2609) glass same (fluorine or F) same Dop\$4
 - (3) (glass same (fluorine or F) same Dop\$4) and (strip\$4 adj dop\$4)
 - (39) (glass same (fluorine or F) same Dop\$4) and ((strip\$4 or remov\$3) adj dop\$4)
- Favorites
- Tagged (7)
- UDC
- Queue
- Trash

Search List Browse Queue Clear

DBs USPAT EPO JPO DERWENT Buletins

Default operator OR

Highlight all hit terms initially

glass same (fluorine or F) same Dop\$4



BRS Term SART Form Image Text HTML

U	I	Document ID	Issue Date	Pages	Title	Current OR	Current XRef	Retrieval Class
---	---	-------------	------------	-------	-------	------------	--------------	-----------------